


# VCF-5K16HDB 5MP

## AHD 紅外線攝影機



## 商品規格

影像元件-	1/2.5" CMOS 影像感應器
信號模式-	NTSC/PAL
影像訊號處理系統-	數位訊號處理系統
視覺角度-	3.6mm
有效像素-	2608 (水平) × 1952 (垂直)
解析度-	5MP@20fps
輸入電壓-	DC 12 ± 1V
消耗功率-	120mA (IR Off); 330mA (IR On)
ICR-	支援
電子快門-	自動
自動白平衡-	自動
自動增益-	自動
信噪比-	≥50dB
日夜轉換-	支援
LED顆數-	8 PCS
投射距離-	30M
紅外線波長-	850nm
最低照度-	0.2 LUX
輸出-	AHD / TVI / CVI / CVBS
語言-	英語/簡中/繁中/俄語/ 義大利語/葡萄牙語
工作溫度-	-20°C~85°C
尺寸 (W×D×H)-	Φ99 × 72 mm
重量-	大約185g

## 安全注意選項

×使用本產品之前，請確定您已閱讀下列的安全注意事項。  
並請確定您操作產品的方法是正確的。

- 請存放本器材於兒童與嬰兒無法觸碰的地方
- 請只使用建議的電源
- 請勿嘗試將產品拆開、改裝或加熱
- 避免使產品丟落地上或受猛烈撞擊
- 要避免受傷，請勿在產品跌下後或損毀時觸碰產品的內部
- 如產品冒煙、發出異味或有其他異常，請立刻停止操作產品
- 請勿使用有機溶劑，如酒精、苯或油漆稀釋劑清潔產品
- 請勿讓任何液體或異物進入機器
- 請勿將電池置於熱源附近，或暴露於火焰中
- 請勿使用濕手觸碰電源線
- 請勿將本器材用於超出指定電壓的電源插座或線路配件
- 請勿使用損毀的電源線或插頭，或沒有完全插入電源插座
- 請避免端子或插頭接觸到金屬物件（如針或鑰匙）或污漬

## OSD控制線(選配)



AHD or CVBS or TVI or CVI輸出，使用OSD切換模式


- CVBS模式:持續壓OSD上鍵5秒鐘
- CVI模式:持續壓OSD下鍵5秒鐘
- AHD模式:持續壓OSD左鍵5秒鐘
- TVI模式:持續壓OSD右鍵5秒鐘

## OSD操作選單

曝光	←.....	亮度/曝光模式
白平衡	←.....	模式
日夜切換	←.....	模式/智能紅外
圖向增強	←.....	對比度/銳度/飽和度/3D降噪/2D降噪/DWDR
視頻設置	←.....	模式/制式
語言	《繁體》	
恢復出場設置		
保存退出		
退出		

# VCF-5K16HDB 5MP

## AHD IR Camera



## SPECIFICATIONS

<b>Pick Up Element-</b>	1/2.5" CMOS sensor
<b>Video System-</b>	NTSC/PAL
<b>Image Signal Process-</b>	Digital Signal Processor
<b>Lens-</b>	3.6mm
<b>Number Of Pixel-</b>	2608 (Horizontal) x 1952(Vertical)
<b>Horizontal Resolution-</b>	5MP@20fps
<b>Power Supply-</b>	DC 12 ± 1V
<b>Power Consumption-</b>	120mA (IR Off) : 330mA (IR On)
<b>ICR-</b>	Support
<b>Electronic Shutter-</b>	Auto
<b>White Balance-</b>	Auto
<b>Gain Control-</b>	Auto
<b>S/N Ratio-</b>	≥50dB
<b>Day Night Auto Switch-</b>	Support
<b>LEDs-</b>	8 PCS
<b>IR Range-</b>	30M
<b>IR Wavelength-</b>	850nm
<b>Minimum Illumination-</b>	0.2 LUX
<b>OUTPUT-</b>	AHD or CVBS or TVI or CVI (Default setting: AHD Mode)
<b>Language-</b>	English / Simplified Chinese / Traditional Chinese / Russian / Italian / Portuguese
<b>Operating Temperature-</b>	-20°C~85°C
<b>Dimensions (H×W×D)-</b>	Φ99 × 72 mm
<b>Weight-</b>	About 185g

## OSD Manual

AE	←	.....	..BRIGHTNESS / EXPOSURE MODE
AWB	←	.....	..MODE
DAY/NIGHT	←	.....	..MODE / SMART IR
IMAGE ENHANCE	←	.....	..CONTRAST / SHARPNESS / SATURATE /3DNR / 2DNR /DWDR
VIDEO SETTING	←	.....	..HD / STANSARD
LANGUAGE	《	ENGLISH	》
RESET			
SAVE&EXIT			
EXIT			


## Safety Precautions

× Before using the product, please ensure that you read the safety precautions described below.

Always ensure that the product is used correctly.

- Use only recommended power sources.
- Do not attempt to disassemble, alter or apply heat to the product.
- Avoid dropping or subjecting the product to severe impacts.
- To avoid the risk of injury, do not touch the interior of the product if it has been dropped or otherwise damaged.
- Stop using the product immediately if it emits smoke, a strange smell, or otherwise behaves abnormally.
- Do not use organic solvents such as alcohol, benzene, or thinner to clean the product.
- Do not allow liquids or foreign objects to enter the camera.
- Do not place the camera near or in direct flame.
- Do not handle the power cord with wet hands.
- Do not use the equipment in a manner that exceeds the rated capacity of the electrical outlet or wiring accessories.
- Do not use if the power cord or plug are damaged, or not fully plugged into the outlet.
- Do not allow dirt or metal objects (such as pins or keysto contact the terminals or plug.

## OSD Controller(option)



AHD or CVBS or TVI or CVI output, switching modes using OSD:

- CVBS mode: Press and hold UP button for 5 seconds
- CVI mode: Press and hold DOWN button for 5 seconds
- AHD mode: Press and hold LEFT button for 5 seconds
- TVI mode: Press and hold RIGHT button for 5 seconds